## JOB QUOTE



WARD LEONARD 8100 FM 2234 MCHARD ROAD HOUSTON, TX 77053 **UNITED STATES** (713)-748-0702

QUOTE NO **QUOTE DATE PAGE** 

s CITY OF AUSTIN 911 LINGER LANE

Т

0

AUSTIN, TX 78721

00207386 8/27/2020

CIT103

0 CITY OF AUSTIN

911 LINGER LANE

D **AUSTIN, TX 78721** 

Т 0

**CUSTOMER PO#** PO RELEASE# **MISC NUMBER** 

#### NAMEPLATE DATA

No nameplate data

#### SPECIAL INSTRUCTIONS

No special instructions

DESCRIPTION UNIT QTY **UNIT PRICE EXTENSION** 

### SCOPE OF WORK

Inspection and cleaning of (1) TECO Westinghouse 1500 HP, 1186 RPM, 12470 Volt motor; Vertical Motor shall include at a minimum the following:

- \* Arrive onsite and complete all safety meetings.
- \* Complete a JSA on the Scope of Work provided.
- \* Lock Out & Tag Out all potential energy sources.
- \* Drain oil from motor upper reservoir \* Remove upper bearing bracket cover lid.
- \* Visual inspect and document conditions of bearing assembly and housing internals.
- \* Hand clean upper bearing housing, as needed.
- \* Perform bore scope inspection of upper bearing bracket standpipe area and bottom of bracket.
- \* Visually inspect and document conditions of motor.
- \* Disassemble motor upper bearing support as necessary and perform visual inspection of stator, rotor, bearings, and other components.
- \* Inspect visible areas of motor windings for oil saturation and document.
- \* Investigate for cause of leak in upper oil reservoir.
- \* Perform a leak test, if possible.
- \* Repair upper oil reservoir as necessary to correct the leak.
- \* Install new column type oil level sight gauge on upper oil.
- \* Install upper bearing bracket cover / lid.
- \* Fill motor oil reservoir to the appropriate level with customer supplied oil.
- \* Return motor to service condition. \* Perform mechanical inspections of bearings, seals and shaft bearing journals.
- \* Provide a report of all finding of the motor to include recommendations for modification and/or repairs.

# FIELD SERVICE TECHNICIAN

We estimate (2) Technicians (8) Hours each to complete the Work Scope.

\* If there is any delays as in scaffolding assembly, crane usage or etc. this would be and added cost to the quote.

FIELD SERVICE TRAVEL

FIELD SERVICE MOD/DEMOB

**MILEAGE** 

**HOTEL** 

# **JOB QUOTE**



WARD LEONARD 8100 FM 2234 MCHARD ROAD HOUSTON, TX 77053 **UNITED STATES** (713)-748-0702

**QUOTE NO** 00207386 QUOTE DATE 8/27/2020 **PAGE** 2

CIT103

О

Т 0

CITY OF AUSTIN 911 LINGER LANE **D** AUSTIN, TX 78721

T 0

s CITY OF AUSTIN

H 911 LINGER LANE I AUSTIN, TX 78721

**CUSTOMER PO#** PO RELEASE# MISC NUMBER

## Quotation

Valid for 30 calendar days from the above date Estimate does not include Sales Tax if applicable. Estimate does not include Freight if applicable. Based upon our Standard Terms and Conditions

Received	Date:	
By:	Date:	